

aip@skyguide.ch

TEL: 043 931 61 68
AFTN: LSSAYOYX

Schweiz
Svizzera

Suisse
Switzerland

skyguide

AIP Services

CH-8602 WANGEN BEI DÜBENDORF

VFR Manual

SUP 003/26

Publication
date:

09 JUL 2026

Geneva Airport (LSGG):

Construction works - Slab replacement on Taxiways A, OUTER and LINK 4

Folgende SUPPLEMENT Seiten sind im VFR Manual **einzufügen**:

Les pages SUPPLEMENT suivantes sont à **insérer** dans le VFR Manual:

Le pagine SUPPLEMENT seguenti devono essere **introdotte** nel VFR Manual:

Insert the following SUPPLEMENT pages in VFR Manual:

Seite:

Page:

Pagine:

Page:

gültig bis:

valable jusqu'au:

valido fino:

valid to:

VFR SUPPLEMENT 1/2

(EN/Chart)

UFN

Alle **zur Zeit gültigen** SUP-Blätter sind in der **CHECK LIST** des VFR Manual mit **S** gekennzeichnet.

Toutes les pages **SUP en vigueur** du VFR Manual sont désignées par un **S** dans la **CHECK LIST**.

Tutte le pagine **SUP attualmente in vigore** sono contrassegnate da una **S** sulla **CHECK LIST** del VFR Manual.

All **SUP** pages **currently in force** are marked with a **S** on the **CHECK LIST** of VFR Manual.

Geneva Airport (LSGG):**Construction works - Slab replacement on Taxiways A, OUTER and LINK 4****DATES AND HOURS**

Start: 09 July 2026

End: December 2027 EST

- Works are carried out daily between 2300 and 0545 LT EST.
- Exact dates, affected areas and associated restrictions are published by NOTAM.

PURPOSE

This AIP Supplement informs aircraft operators and flight crews of temporary works related to the replacement of concrete slabs at Geneva Airport (LSGG) and to raise awareness regarding the detailed NOTAMs.

SCOPE

The works affect specific, operationally critical paved areas and the ATS / Geneva Apron interface. They may result in temporary unavailability of some taxiway centreline lights on some taxilanes, runway exits and apron taxiways.

OPERATIONAL IMPACT

- Temporary closure of taxilanes within the work area.
- Temporary closure of runway exits.
- Taxiway centerline lights in the affected area, including areas adjacent to the work site, are temporarily switched off.
- Taxilane centerline and apron markings may be temporarily unavailable within the affected apron areas.
- Alternative taxi routes and apron procedures will be instructed by ATC resp. AMS.
- No impact on runway operations or instrument flight procedures.
- Follow-me service compulsory in adverse weather conditions, at night and in low-visibility conditions. If needed, follow-me service can be requested at any other time by the crews.
- Normal daytime configuration restored by 0545 LT unless otherwise published by NOTAM.

SAFETY MEASURES

- Work areas are delimited, marked and lighted in accordance with applicable standards.
- Access to the work area is restricted to authorised personnel and vehicles only.

CONTACT

Email: aip@gva.ch

Email: operations.travaux@gva.ch

ARP WGS-84	AD ELEV ft
46° 14' 18" N / 006° 06' 34" E	1411

LGT	ALS	RTHL	RTIL	VASIS	RTZL	RCLL	REDL	YCZ	RENL	TWY
04				PAPI 3° MEHT 18.5 m	-					
22	✓	✓	✓	PAPI 3° MEHT 19.94 m	✓	✓	✓	✓	✓	✓

Surface	
Apron	CONC/ASPH
TWY	CONC

ATIS	135.580
DEL+GND NORTH	121.680
TWR	118.705


LEGEND

- A TWY
- APRON BDRY
- AIRPORT BDRY
- (H) ↗ AD INFO 2

WIP BY SECTOR
Slab replacements are carried out daily
between 2300 LT and 0545 LT ESTIMATED

Touchdown 22
single engine VFR ACFT

Works may result in temporary unavailability
of taxiway/taxilanes centreline lights throughout
the affected area



COR: SUP 26/003